[USN] SHL-2659 (JCAB)

## DEPARTURE ROUTE DESCRIPTION

(Continued)

## **SOUTHWEST THREE:**

TAKE-OFF RUNWAY 03: Turn right, climb via AME VOR/DME R-227 to PINNE. Cross PINNE at assigned or specified altitude.

TAKE-OFF RUNWAY 21: Climb runway heading to 1000, turn right, climb via AME VOR/DME R-227 to PINNE. Cross PINNE at assigned or specified altitude.

<u>TOKUNOSHIMA TRANSITION:</u> After PINNE, intercept TKE VOR/DME R-096 to TKE VOR/DME.

ERABU TRANSITION: After PINNE, intercept ONC VORTAC R-046 to ONC VORTAC (225° bearing to ON NDB).